



TRAVEL ADVISORY GSP EXIT 105

Mar 10 2023

Ramp from Parkway **Local Lanes** at Exit 105 **to close** for new phase of construction

Construction on the Garden State Parkway Exit 105 Project will switch to a new phase this weekend as the exit from the southbound Express Lanes reopens and the exit from the southbound Local Lanes closes for construction.

Here's what drivers need to know:

- Southbound drivers who want to exit onto Route 36 will need to be in the Express Lanes during the new phase of construction. There will be no access to exit 105 from the southbound Local Lanes.
- A temporary crossover has been built about three miles north of Exit 105 to allow one last opportunity for southbound drivers to move from the Local Lanes to the Express Lanes before they reach Exit 105.
- Northbound drivers will not be affected by the change to the new phase of construction.
- An entrance ramp from Route 36 to the northbound Parkway that was closed during the previous phase of construction has reopened.
- The entrance ramp from Route 36 to the southbound Parkway will remain closed. Drivers who want to enter the southbound Parkway are directed by sign to use Route 18 and Route 66 to access the Parkway at Interchange 102.